

## FH-400 Case STX AccuSteer Kneeler

## **Undercarriage Installation Instructions**

## Caution:

- Always use precaution when working around any equipment.
- Always wear safety glasses.
- Follow tractor manufacturer's safety guidelines when installing this product.
  - **1.** Read all instructions prior to installation.
  - 2. Remove existing toolboxes and tow cable holder if equipped.
  - 3. Position the undercarriage (U/C) under the tractor and center with the frame of the tractor.
  - 4. Raise the front of the U/C to within 1/2" from the frame of the tractor.
  - **5.** Start 4 20mm x 90mm bolts (PN: 16-1510) with a large washer (PN: 57-8836) on each bolt into the vertical slots at the front of the U/C. Tighten the bolts until the washers contact the U/C. See attached diagram for clarification.
  - **6.** Attach the rear of the U/C to the front side of the front axle with 4 20mm x 50mm bolts (PN: 16-1878) and a 3/4" flat washer (PN: 57-20747) on each bolt. Finger tighten the bolts.
  - 7. Torque the 20mm x 50mm spacer bolts to 432 ft-lbs.
  - 8. Proceed with torqueing the vertical 20mm x 90mm bolts to 432 ft-lbs.
  - **9.** Use the side frame holes as guides and drill 6 1" holes through the side of the tractor frame.

Caution: When drilling, be aware of all parts behind the material being drilled so that you do not mistakenly hit or puncture components on engine side of tractor frame.

- **10.** Install 6 1" x 3" bolts (PN: 16-20562) with a 1" heavy washer (PN: 57-3682) in the previously drilled holes. See attached diagram for clarification.
- **11.** After the 6 1" bolts are through the tractor frame, attach with a 1" heavy washer (PN: 57-3682) and 1" nut (PN: 70-20599) on each bolt.
- **12.** Torque all 1" bolts to 903 ft-lbs.
- **13.** After first 8 hours of use, re-torque all bolts.
- **14.** Check all fasteners regularly to ensure proper operation of equipment.

